



STATE OF ILLINOIS  
ENVIRONMENTAL PROTECTION AGENCY

EPA Region 5 Records Ctr.



358226

NARRATIVE INSPECTION REPORT DOCUMENT

Date of Inspection: 4/23/90 Inspector: JAMES HAENNICKE  
Site Code: 0 3 1 6 0 0 0 0 3 4 County: COOK  
Site Name: LAND & LAKES #3 Time: 11:15-12:05 p.m.

GENERAL REMARKS

Site manager Mark Batherson drove me through LAND & LAKES #3 for a routine inspection. The temperature was 64° F and dry.

As LAND & LAKES awaits a response from MWRDGC for analysis of their liquid treatment effluent, their retention pond has continued to rise. It is near its maximum capacity and word from MWRDGC is anticipated soon.

No violations were noted.

STATE OF ILLINOIS  
ENVIRONMENTAL PROTECTION AGENCY

SITE SKETCH

Date of Inspection: 4/23/90

Inspector: JAMES HAENNICKE


Site Code: 0 3 1 6 0 0 0 0 3 4

County: COOK

Site Name: LAND & LAKES #3

Time: 11:15-12:05

STONY ISLAND



4/23/90

Time: 11:15-12:05

Photograph By:

JAMES HAENNICKE

City: CHICAGO

EPA #: 0316000034

Site Name:

LAND & LAKES #3

Comments:



Photo # 1 Roll # 90-305

Date: 4/23/90

Time: 11:15-12:05

Photograph By:

JAMES HAENNICKE

City: CHICAGO

EPA #: 0316000034

Site Name:

LAND & LAKES #3

Comments:

S.E.

EXCAVATION PIT



Photo # 2 Roll # 90-305